


 $\Gamma$ 

ļ

Г.					- 2 /F				
	Zone 10	Wipe two min total	No stop req'd.	No stop req'd.	2/5				
	Zone 9		No stop req'd.	No stop req'd.			ea		2
Inside Spray Booth	Zone 8	De-mold finished "c" lap part – one minute	No stop req'd.	No stop req'd.	Fig-2		5 Cure	5 Cure	
	Zone 7	No stop req'd.	Rotate; Flip and Chop; Barrier Coat – two min. total.	Foam; Base; Rotate one min. total		6 Cure and queue			
	Zone 6	oğ	Cure/ Queue	Cure/ Queue			49	Roll,	1-3
	Zone 5a/5b	Cure	Cure	Cure			2a Cover	\\\ 4\frac{5}{6}	
	Zone 4	Queue (4a)	Queue (4b) Roll; Trim	Queue (4a)			Gel 1	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	_
	Lap	To lap B	To lap C	To lap A			10b	24A-	
	Zone 2		First Chop Coat Spray	Cover Coat Spray		Spray	10a Wipe	100	
	Zone 1	Gelcoat				Pull, Wipe	9 Wipe		Fig-3
	Mold Lap	Lap 1 "A"	Lap 2 "B"	Lap 1 "C"					Fi


 $\Gamma$ 

Г



╛

Γ-



┙